

Imray Correction Notice

ICC42

30 August 2012

Chart C42 WGS 84

Edition Jul 2009

Date of printing Jul 2009

The following corrections should be noted:

1 Île d'Oléron westwards

Substitute:

Dangerous Wk symbol *ED* for Wk *PA* in 45°59'·5N 1°30'·0W.

Wk *PD* for dangerous Wk *PA* in 45°58'·5N 1°42'·8W (ILNW 370/09)

2 Santander northwestwards (buoy removed - see ILNW 432/11)

Insert Y *ODAS* Lt buoy FI(5)Y.20s in 43°30'·57N 3°52'·88W (ILNW 374/09)

3 Approaches to Port de Bayonne

Insert Y pillar Lt buoy FI(4)Y.15s (2 buoys) with x topmk in 43°31'·95N 1°36'·86W. (ILNW 61/10)

4 Arcachon, Chenal du Teychan (Plan A)

Insert dangerous wk sym in 44°40'·40N 1°08'·91W (ILNW 196/10)

5 Santander, Isla de Mouro (Main chart & Plan H)

Amend Lt FI(3)21s37m7M to FI(3)16s37m11M in 43°28'·39N 3°45'·35W. [FI(3)11M on main chart]. (ILNW 248/10)

6 Approaches to Bayonne

Insert *A/S* at safe water Lt buoy LFI.10s in 43°32'·58N 1°32'·79W (ILNW 377/10)

7 San Sebastian northeastwards (Correction amended - see ILNW 185/11)

Amend Lt duration Mo(A)6s to 7s at safe water Lt buoy in 43°21'·19N 1°56'·12W (ILNW 450/10)

8 Santander, Cabo Mayor

Delete fog signal Horn(2)40s at Lt in 43°29'·42N 3°47'·45W (ILNW 95/11)

9 Santander, Apps to Pedreña (Plan H)

Amend Lt FI(2)R.7s at R pillar Lt buoy to FI.R.5s in 43°26'·96N 3°46'·52W (ILNW 96/11)

10 Castro Urdiales

Delete fog signal SirenMo(C)60s at Lt in 43°23'·08N 3°12'·88W (ILNW 114/11)

11 Embouchure de la Gironde southwards

Insert Y can Lt buoys with x topmks:

FI.Y.4s in 45°10'·55N 1°18'·60W

FI(4)Y.15s in 45°09'·05N 1°16'·30W

FI(5)Y.20s in 45°06'·08N 1°25'·99W (ILNW 116/11)

12 Approaches to Pasaia

Insert *A/S* at safe water Lt buoy Mo(A)7s in 43°21'·19N 1°56'·12W (ILNW 185/11)

13 Approaches to La Gironde

Insert *A/S* at **BXA** Lt buoy in 45°37'·53N 1°28'·68W (ILNW 228/11)

14 Île de Ré southwestwards

Insert *A/S* at safe water Lt buoy Iso.4s *PA* in 46°05'·63N 1°42'·44W (ILNW 245/11)

15 Plateau de Rochebonne

Insert *A/S* at **Rochebonne SE** Lt buoy in 46°09'·21N 2°21'·12W (ILNW 246/11)

16 Entrance to La Gironde, Plateau de Cordouan westwards

Insert drying wk symbol in 45°35'·56N 1°12'·30W (ILNW 269/11)

17 Pte d'Arcachon westwards

Substitute *Obstn* sym for depth 6-4m in 44°32'·50N 1°17'·55W and add isolated danger pillar buoy close W. (ILNW 276/11)

18 île d'Oléron westwards (*correction deleted - see ILNW 400/11*)

Insert dangerous wk sym, and assoc. lgd (*buoyed*), in 45°53'·17N 1°38'·59W (ILNW 330/11)

19 Bilbao, Real Club Marítimo del Abra (Plan F)

Move Lt Oc.R.4s in 43°19'·84N 3°00'·91W to 43°19'·79N 3°00'·94W (ILNW 399/11)

20 Île d'Oléron westwards

Delete dangerous wk sym, and assoc. lgd (*buoyed*), in 45°53'·17N 1°38'·59W (ILNW 400/11)

21 Santander northwestwards

Delete Y ODAS Lt buoy FI(5)Y.20s in 43°30'·57N 3°52'·88W.

Insert Y wind turbines FI(5)Y.20s in:

43°30'·49N 3°52'·96W

43°30'·77N 3°52'·28W (ILNW 432/11)

22 Approaches to La Gironde

Insert *Obstn* symbol in:

45°37'·10N 1°25'·90W

45°36'·60N 1°26'·30W (ILNW 443/11)

23 Bilbao (Plan F)

The quay to the south of Dique de Ciérvana has now been fully reclaimed (centred on 43°21'·65N 3°04'·09W).

Full details will be included on the next edition of this chart. (ILNW 110/12)

24 Cap Ferret (Main chart & Plan A)

Amend range of Lts FI.R.5s53m27M & Oc(3)12s46m14M to 22M & 11M respectively in 44°38'·75N 1°14'·93W (ILNW 164/12)

25 Approaches to Bilbao

Insert Y spher Lt buoy with x topmk FI(5)Y.20s in 43°28'·39N 2°54'·33W (ILNW 342/12)

26 Bassin d'Arcachon (Plan A)

Due to the changing depths in the approaches to Arcachon, navigation aids from Chenal d'accès (44°34'·40N 1°18'·25W) through to the marinas at Arcachon may be different to those charted.

Mariners are advised to consult the local authorities for further details and to navigate with caution in these waters. (ILNW 343/12)